

New Front Entrance –
Replaces Leaking Skylight and Canopy that is aging / More Open and Welcoming for People



New Front Entrance –
View from left side of the parking lot as you walk into the building



Inside Main Foyer –

More open with natural light / Replaces current stairs that are safety concern due to angle of stairs



a+LINK
architecture inc.
preserve + create + sustain

Main Foyer –

Looking approximately from where the current stairs are today – Café remains on the left side



New Back Entrance –
New Entrance for Kids Ministry, Programs Upstairs, and Direct Access to Gymnasium



a+LINK
architecture inc.
preserve + create + sustain

New Back Entrance –
Different angle from last picture



First look inside back entrance.

Stairs are direct down to gymnasium / Doors close to stairs are current outside doors to that side of the building.



Inside the new back entrance –
New hallway that takes you to a new Children’s Ministry foyer and check in area



a+LiNK
architecture inc.
preserve + create + sustain

New Children's Ministry Foyer and Check In Area –
Replaces an outdoor area currently called the Courtyard and covers over where water is leaking into the building.



a+LiNK
architecture inc.
preserve + create + sustain

View from Walking Out of Auditorium Balcony –
Hall to the left is new from previous pictures / Hall to the right is current hallway to classrooms



